



**BSP for Microsoft* Windows* 8 (Win8,
WES8) 32-bit & 64-bit OS for**

**Intel® Atom™ Processor E3800 Product
Family,**

Intel® Celeron® Processor N2807 &

Intel® Celeron® Processor J1900

Maintenance Release 1

Release Notes

October 2015

Version 001 for Software Maintenance Release 1



You may not use or facilitate the use of this document in connection with any infringement or other legal analysis concerning Intel products described herein. You agree to grant Intel a non-exclusive, royalty-free license to any patent claim thereafter drafted which includes subject matter disclosed herein

No license (express or implied, by estoppel or otherwise) to any intellectual property rights is granted by this document.

All information provided here is subject to change without notice. Contact your Intel representative to obtain the latest Intel product specifications and roadmaps.

The products described may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Copies of documents which have an order number and are referenced in this document may be obtained by calling 1-800-548-4725 or by visiting: <http://www.intel.com/design/literature.htm>

Intel technologies' features and benefits depend on system configuration and may require enabled hardware, software or service activation. Learn more at <http://www.intel.com/> or from the OEM or retailer.

No computer system can be absolutely secure.

Intel, Atom, Celeron, and the Intel logo are trademarks of Intel Corporation in the U.S. and/or other countries.

*Other names and brands may be claimed as the property of others.

Copyright © 2015, Intel Corporation. All rights reserved.

BSP for Microsoft* Windows* 8 32-bit & 64-bit OS for
Intel® Atom™ Processor E3800 Product Family, Intel® Celeron® Processor N2807 &
Intel® Celeron® Processor J1900 Maintenance Release 1
Release Notes



Contents

| | | |
|------------|---|-----------|
| 1.0 | Introduction..... | 5 |
| 1.1 | Scope of document | 5 |
| 1.2 | System Requirements..... | 5 |
| 1.3 | Acronyms and Terminology..... | 5 |
| 2.0 | Release Summary..... | 7 |
| 2.1 | Release Contents..... | 7 |
| 2.2 | External Dependencies..... | 8 |
| 3.0 | New In This Release | 9 |
| 3.1 | Changes to Existing Features | 9 |
| 3.2 | New Features..... | 9 |
| 3.3 | Unsupported Features..... | 9 |
| 3.4 | Discontinued Features..... | 9 |
| 4.0 | Fixed Issues, Errata, and Known Issues | 10 |
| 4.1 | Fixed Issues | 10 |
| 4.2 | Errata and Known Issues..... | 10 |
| 4.3 | Non-Intel Issues..... | 11 |
| 5.0 | How to Install This Release..... | 12 |
| 5.1 | Recommended OS Update..... | 12 |
| 5.2 | Recommended BIOS Configuration | 12 |
| 5.2.1 | Driver Installation..... | 12 |
| 5.2.2 | Driver Update..... | 13 |
| 5.2.3 | Driver Uninstallation..... | 13 |
| 6.0 | Best Known Configuration..... | 14 |
| 6.1 | BKC..... | 14 |

Tables

| | | |
|----------|--|----|
| Table 1. | Acronyms and Terminology..... | 5 |
| Table 2. | Contents of Release Package..... | 7 |
| Table 3. | Drivers in 32-bit and 64-bit Installer Packages..... | 7 |
| Table 4. | Fixed Issues..... | 10 |
| Table 5. | Errata and Known Issues..... | 10 |
| Table 6. | Non-Intel Issues | 11 |
| Table 7. | Recommended BIOS Configuration..... | 12 |
| Table 8. | BKC..... | 14 |



Revision History

| Revision Number | Description | Revision Date |
|-----------------|---------------------------------|---------------|
| 001 | Software Maintenance Release 1. | October 2015 |



1.0 Introduction

1.1 Scope of document

This Maintenance Release 1 document presents the Microsoft* Windows* 8 (Win8, WES8) 32-bit & 64-bit operating system requirements, installation instructions, issues and limitations for the Intel® Atom™ Processor E3800 Product Family, Intel® Celeron® Processor N2XXX, and Intel® Celeron® Processor J1XXX.

Additional information can be found in the related software developer's manual.

1.2 System Requirements

The following operating systems are supported:

- Windows 8 Operating System (32- and 64-bit versions)
- Windows Embedded 8 Standard Operating System (32- and 64-bit versions)

1.3 Acronyms and Terminology

Table 1. Acronyms and Terminology

| Term | Description |
|-------------------|--|
| ACPI | Advanced Configuration and Power Interface |
| BKC | Best Known Configuration |
| CRB | Customer Reference Board |
| DMA | Direct Memory Access |
| GPIO | General Purpose Input/Output |
| HCK | Microsoft Windows Hardware Certification Kit |
| HSIC | High-Speed Inter-Chip |
| HS-UART | High Speed Universal Asynchronous Receiver/Transmitter |
| IBL | Intel Business Link |
| IOTG | Internet of Things Group (an Intel business group) |
| ISP | Image Signal Processor |
| I ² C* | Inter-Integrated Circuit* |
| KSC | Keyboard and System Controller |

BSP for Microsoft* Windows* 8 32-bit & 64-bit OS for
Intel® Atom™ Processor E3800 Product Family, Intel® Celeron® Processor N2807 &
Intel® Celeron® Processor J1900 Maintenance Release 1



| | |
|-------|---------------------------------------|
| LPSS | Low Power Sub-System |
| MR1 | Maintenance Release 1 |
| MSDN* | Microsoft Developer Network |
| SCC | South Cluster Configuration |
| SoC | System on Chip |
| SPI | Serial Peripheral Interface |
| UEFI | Unified Extensible Firmware Interface |
| VIP | Validation Internet Portal |
| WES8 | Windows Embedded 8 Standard |
| Win8 | Windows 8 Enterprise |



2.0 Release Summary

2.1 Release Contents

[Table 2](#) lists the contents of the release package.

Table 2. Contents of Release Package

| Release Package Contents | Version |
|--|-----------------------|
| 333232-001US_Intel_Atom_E3800_Win8_IO_Drivers_Release_Notes_MR1. pdf (this document) | Maintenance Release 1 |
| 333231-001US_Intel_Atom_E3800_Win8_IO_Drivers_Programming_Guide_MR1. pdf | Maintenance Release 1 |
| Intel Atom E3800 Win8 IO Drivers 32Bit.msi | Maintenance Release 1 |
| Intel Atom E3800 Win8 IO Drivers 64Bit.msi | Maintenance Release 1 |

Both the 32-bit and 64-bit installer packages contain the drivers shown in [Table 3](#).

Table 3. Drivers in 32-bit and 64-bit Installer Packages

| Software driver installed on target system | Version | Release Date |
|---|---------------------|--------------|
| GPIO Controller <ul style="list-style-type: none"> • iaiogpio.sys • iaiogpioe.inf • iaiogpioe.sys | 603.9600.1948.30590 | 11/22/2013 |
| SPI Controller <ul style="list-style-type: none"> • iaiospi.sys • iaiospie.inf • iaiospie.sys | 603.9600.1948.28229 | 10/31/2013 |
| I²C* Controller <ul style="list-style-type: none"> • iaioi2c.sys • iaioi2ce.inf • iaioi2ce.sys | 603.9600.1948.29470 | 11/13/2013 |
| HS-UART Host Controller <ul style="list-style-type: none"> • iaLPSS_UART.sys | 1.1.5.1006 | 8/28/2014 |

BSP for Microsoft* Windows* 8 32-bit & 64-bit OS for
Intel® Atom™ Processor E3800 Product Family, Intel® Celeron® Processor N2807 &
Intel® Celeron® Processor J1900 Maintenance Release 1



2.2 External Dependencies

An Intel slave device test driver is used for the HS-UART controller. Customers can use their own slave device drivers for other interfaces.



3.0 New In This Release

3.1 Changes to Existing Features

The HS-UART driver is now supported on Intel® Atom™ E3800 Product Family D0 stepping silicon.

3.2 New Features

None

3.3 Unsupported Features

- GPIO driver
 - Multiplexing
 - Pin query
- HS-UART
 - Software Flow Control
- Legacy graphic card is not supported in Win8 64-bit and WES8 64-bit operating systems in 64-bit IOTG BIOS
- SD OS Boot is not supported in Win8 (32- and 64-bit) and WES8 (32- and 64-bit) operating systems
- DMA feature is not supported in Win8 64-bit and WES8 64-bit operating systems

3.4 Discontinued Features

None



4.0 Fixed Issues, Errata, and Known Issues

4.1 Fixed Issues

Table 4. Fixed Issues

| Issue # | Description of Issue | Implication (Impact) | Resolution |
|---------|---|----------------------|--|
| 4994622 | IO Driver not supported on D0 Silicon Symptom: Yellow bang at HS-UART drivers in Device Manager after installation Affected OS: Win8 / WES8 | All IO Feature | Fixed in MR1 Release |
| 4634827 | Safely remove icon did not appear on taskbar notification area when a USB pen drive is attached Symptom: Safely Remove Hardware and Eject Media is not available Affected OS: Win8, WES8 | USB | Fixed in IOTG BIOS v92_21 |
| 4634881 | Can't find UART test device ACPI\BCM4752 or ACPI\BCM2E1A using 72.11 BIOS after "unhide Unsupported LPSS Device" Symptom: Test device ACPI\BCM2E1A and ACPI\BCM4752 is not showing in Device Manager. User can't test UART by using PuTTY or any test tools Affected OS: Win8, WES8 | LPSS Device | Fixed in IOTG BIOS v80_21 |
| 4634927 | Disable the ISP camera device (VIDEO\INTOF38) in BIOS for Win8 to remove the yellow bang in Windows* device manager. Symptom: ISP camera device showing yellow bang in device manager. Affected OS: Win8, WES8 | ISP Camera | Not supported. Disable the ISP camera from BIOS setting in IOTG v80_21 |

4.2 Errata and Known Issues

Table 5. Errata and Known Issues

| Issue # | Description of Issue | Implication (Impact) | Resolution |
|---------|---|--|--|
| 4634818 | System re-enumeration and disconnect on HSIC device | File transfer fail on HSIC device when any plug/unplug on USB2.0 bottom port | Errata: Silicon Bug. Do not plug/unplug on USB2.0 bottom port during file transfer on HSIC device. |



| Issue # | Description of Issue | Implication (Impact) | Resolution |
|---------|---|---|--|
| 4634569 | Kingston* DataTraveler* Elite 3.0 Not Working on USB2 | Failed to detect USB thumb drive | Errata: Test Tools compatible. Avoid using Kingston DataTraveler Elite 3.0 on USB2 (lower-right USB2.0 port) on Bayley Bay and Bakersport platform |
| 4634845 | System unable to wake up from S3 when CPU core = 1 | System failed to wake up after S3 when change CPU core to 1 | Errata: Silicon logic limitation. Do not set CPU core =1 |
| 4634792 | One bit is occasionally wrong in SPI | 1 bit out of 1000 bits is corrupted on Bayley Bay platform. | Errata: Platform issue. Use Bakersport or Bayley bay Fab 3 light green boards. |
| 4634826 | Keyboard or mouse is unable to wake the system from sleep and hibernate | System failed to wake up with mouse or keyboard attached to the top USB2.0 port on Bayley Bay and Bakersport. | Errata: Hardware limitation. Wake the system with the power switch. |
| 4634816 | Bayley Bay system shutdown after BIOS stage when booting up with SD card plug in. | System failed to boot up if SD card is connected | Errata: Platform Issue. Suggested to use Bakersport. |

4.3 Non-Intel Issues

Table 6. Non-Intel Issues

| Issue # | Description of Issue | Implication (Impact) | Resolution |
|---------|---|---|---|
| 4634526 | Recorded sound is low and not clear | Voices recording sound is low and not clear | User can adjust the Microphone Boost Setting in Windows to increase the recording volume. |
| 4634926 | Win8 HS-UART with DMA gets unexpected failed test cases when running Microsoft* Windows* HCK Test Suite | Microsoft Windows HCK Test Suite test cases fails | No resolution from Intel as DMA driver is from Microsoft Inbox driver. |



5.0 How to Install This Release

5.1 Recommended OS Update

The following operating system update is recommended to be installed:

- Microsoft* Update KB2756872 for Win8 and WES8 operating systems is required to enable DMA features in the 32-bit operating system and to remove yellow bangs in Windows* Device Manager.

<http://www.microsoft.com/en-us/download/details.aspx?id=34879>

5.2 Recommended BIOS Configuration

Table 7. Recommended BIOS Configuration

| BIOS Selection | Configuration |
|--|---|
| OS Selection | Device Manager -> System Setup > Boot > OS Selection > Windows8.X |
| Secure Boot | To disable UEFI Secure Boot Device Manager -> System Setup > Boot > UEFI Security Boot > Select "Disable" |
| LPSS & SCC Configuration | To Enable ACPI Mode: Device Manager > System Setup > South Cluster Configuration > LPSS & SCC Configuration > LPSS & SCC Devices Mode > Select "ACPI Mode" To enable SD card for Windows: Device Manager > System Setup > South Cluster Configuration > LPSS & SCC Configuration > SCC SD Card for Windows > Select "Enable" |
| Intel® High Definition Audio (Intel® HD Audio) Configuration | To enable Intel HD Audio: Device Manager > System Setup > South Cluster Configuration > Audio Controller > Select "Enable" |

5.2.1 Driver Installation

Intel recommends that the following steps be run as administrator:

1. Execute Intel Atom E3800 Win8 IO Drivers 32bit.msi (or 64bit)
2. Check the "I accept the terms in the license agreement" and click "Next".
3. Choose the directory for the installation and click "Next".
4. Choose the "Complete" option for the installation of all drivers and click "Next".
Alternatively, choose "Custom" to choose specific IO drivers to be installed.



5. Click "Install" and wait for the installation to complete.
6. Click "Finish" to exit the installer.
7. Reboot the system for changes to take effect.

5.2.2 Driver Update

1. Open "Device Manager"
2. Identify existing drivers in your system with the following strings for the driver that you want to update, namely:
 - "System Devices\ GPIO Controller"
 - "System Devices\ I2C Controller"
 - "System Devices\ SPI Controller"
 - "System Devices\ HS-UART Controller"
3. Choose "Update Driver Software" – "Browse my computer for driver software" – "Let me pick from a list of device drivers" – "Have Disk" then go to the specific IO driver folder to install the driver.

Note: If possible, check the time stamp of the driver in the target to ensure that the right binaries are used.

5.2.3 Driver Uninstallation

Uninstall the IO driver from Control Panel\All Control Panel Items\Programs and Features.



6.0 Best Known Configuration

6.1 BKC

Table 8. BKC

| Hardware Category | Description | Rev/Type/Source |
|---|---|---|
| CRB | Bayley Bay Bakersport | FAB3 REV03 FABB |
| SoC | Intel® Atom™ Processor E3800 Family Intel® Celeron® Processor N2XXX Intel® Celeron® Processor J1XXX | Up to D0 –I Up to C0 – D Up to C0 - M |
| Display | VGA | |
| Memory | Bayley Bay: 4 GB DDR3 (2x2GB) Bakersport: 2 GB DDR3 (1x2GB with ECC) | |
| CRB BIOS | Win8 32-bit and WES8 32-bit operating systems: BYTICRB_IA32_R_SPI_0093_41_Sec_Enabled Win8 32-bit and WES8 64-bit operating systems: BYTICRB_X64_R_SPI_0093_41_Sec_Enabled | Intel (IBL#: 559868) |
| KSC | v03.14 | Intel (IBL#: 559868) |
| Operating System | Windows* 8 Enterprise Build 9200 Windows* Embedded 8 Standard Build 9200 | MSDN* |
| Intel® Graphics Driver | 15.33.39.64.4276 (64 bit) 15.33.39.4276 (32 bit) | VIP Kit#: 109495 VIP Kit#: 109494 |
| Intel® Serial IO GPIO Driver | 603.9600.1948.30590 | Intel |
| Intel® Serial IO I2C Driver | 603.9600.1948.29470 | |
| Intel® Serial IO SPI Driver | 603.9600.1948.28229 | |
| Intel® Serial IO UART Driver | 1.1.5.1006 | |
| Intel® Chipset Driver Software | 10.1.1.7 | VIP Kit#: 107514 |
| Intel® Trusted Execution Engine (Intel® TXE) FEATure FW and tools for Intel® Atom™ Processor E3800 Product Family | 1.1.4.1145v3 | VIP Kit#: 110908 |
| Intel® TXE FEATure FW and tools for Intel® Celeron® Processor N2920 and Intel® Celeron® Processor J1900 | 1.1.4.1145 | VIP Kit#: 107987 |

Best Known Configuration



| | | |
|---|----------------|-----------------|
| Intel® Sideband Fabric Device (Intel® MBI) Driver | 1.70.305.16316 | VIP Kit#: 58443 |
|---|----------------|-----------------|

BSP for Microsoft* Windows* 8 32-bit & 64-bit OS for
Intel® Atom™ Processor E3800 Product Family, Intel® Celeron® Processor N2807 &
Intel® Celeron® Processor J1900 Maintenance Release 1