

Intel® PRO/10/100/1000/10000 Software Release 1 – Gold+CAT Release (Nyssa)
With Intel(R) PROSet for Windows* Device Manager
Critical Issues Currently Under Investigation
04/14/05

Intel LAN Access Division

This document as well as the software described in it is furnished under license and may only be used or copied in accordance with the terms of the license. The information in this manual is furnished for informational use only, is subject to change without notice, and should not be construed as a commitment by Intel Corporation. Intel Corporation assumes no responsibility or liability for any errors or inaccuracies that may appear in this document or any software that may be provided in association with this document.

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Except as permitted by such license, no part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means without the express written consent of Intel Corporation.

Contact your local Intel sales office or your distributor to obtain the latest specifications and before placing your product order.

Copyright © Intel Corporation 2005

*Third-party brands and names are the property of their respective owners.

Please Note

- **Jumbo Frames are not supported on 82573E (Tekoa) silicon.**
- **Lakeport systems using the Silicon Validation BIOS require the following configuration change to support DOSODI and NDIS2 (SCR 44287):**

In the BIOS setup, go to the SV menu. Under "SV Setup Options", change the value of "PCI Exp Bridge ISA Enable" from "Auto" to "Disabled".

Detail: This problem appears to be related to the specific I/O address assigned to the Tekoa LAN function by the BIOS. As configured by the BIOS, I/O reads to adapter registers always fail, returning 0xFFFFFFFF. This causes the driver to be unable to read the adapter EEPROM or configure the adapter for operation and thus it fails to load.

The issue also affects Intel Boot Agent but is not corrected through the use of the work-around. We instead recommend upgrading to the release BIOS.

Efforts are underway to root-cause this issue in the Lakeport hardware.

- **As of this release, no new Device IDs or features will be added to the Intel® PROSet application. All new device support and features will only be added to the new Intel® PROSet for Windows* Device Manager application.**
- **Intel's support for Windows NT 4.0 has been moved to Sustaining mode 2. New silicon support will not be added to the operating system and only serious customer-requested bug fixes will be acted upon.**
- **When upgrading an earlier version of Intel PROSet for Windows Device Manger, teams & VLAN names are not always restored correctly. This issue will be corrected in the next release. (SCR 45638 for details).**

Issues List

- **None**